

Play Equipment:  
 Metal Climber  
 Bars  
 Posts  
 6 Swings  
 TB  
 VB


2.8 Acres  
 Condem. in 1910  
 \$23,851 = '08 BF.  
 "...for park + parkway purposes."  
 801 E. 50th St.

1st enclosed play field - wire fence w/ gates  
 and locks - 1911  
 Shelter House (1951) \$7,055 = Cum. Res. + St. Fds.  
 replaced original one built in 1911.  
 Community clubs: \$1,000 = 1943

141

UNIVERSITY P.G.


091676



141

YEAR OF IMPROVEMENT: 1983  
 COST OF IMPROVEMENT: \$70,935.15  
 DESIGNER: CONSERVATION COMPANY  
 CONTRACTOR: LANDSCAPE SERVICES INC.

01 06 86



Play Equipment:  
 Metal Climber  
 = Bars  
 Posts  
 6 Swings  
 TB  
 VB

2.8 Acres  
 Condem. in 1910  
 \$23,851 = '08 BF.  
 "... for park + parkway purposes."

801 E. 50th St.

1st enclosed play field - wire fence w/ gates and locks - 1911  
 Shelter House (1951) \$7,055 = Cum. Res. + St. Fds. replaced original one built in 1911.  
 Community clubs: \$1,000 = 1943

141

UNIVERSITY P.G.  
 SHEET 2 OF 2

091676