Housing Code Violation Examples for Committee on the Built Environment

May 12, 2010

Presented by

Karen White



Tenant’s door to rented space in between walls
Delridge Way SW



Egress window issue

Bed

Broken wall cover
15th Avenue NE

Outside view of boarded broken window
15th Avenue NE

Inside view of boarded broken window

15th Avenue NE

Exposed ceiling covering in kitchen with exposed electrical wiring

No ceiling

Delridge Way SW

Damaged kitchen ceiling
Delridge Way SW

Low ceiling, crawl space unit, dirt floor
S Cloverdale

Crawl space unit
S Cloverdale

Ceiling hole caused by upstairs leak

Kitchen/Bath Combo
Fremont

Hanging lock on a broken door
Fremont

Mold on bedroom ceiling
North Seattle

Mold on living room ceiling
North Seattle

Mold on living room ceiling
North Seattle

Entrance to furnace room

Furnace room